

South Butler County School District

Lead and Copper Sampling Results - Intermediate Elementary

Orange highlight indicates result is over 1/2 of DEP Action Level	Yellow highlight indicates result is at/over the DEP Action Level	PA DEP Copper Action Level - 1.3 mg/L	PA DEP Lead Action Level - 0.015 mg/L
Sample Date	Location	Copper Result (mg/L)	Lead Result (mg/L)
5/26/2017	211-213 Fountain - Right	0.085	<0.001
5/26/2017	Room 212 Sink	0.097	0.009
5/26/2017	Room 212 Bubbler	0.115	0.006
5/26/2017	Room 210 Sink	0.148	0.015
5/26/2017	Room 210 Bubbler	0.119	0.012
5/26/2017	Library Sink	0.299	0.048
5/26/2017	Library Bubbler	0.101	0.004
5/26/2017	Library Work Room	0.101	0.003
5/26/2017	Room 208 Sink	0.102	0.002
5/26/2017	Room 208 Bubbler	0.072	<0.001
5/26/2017	Room 208 Back Sink	0.150	0.061
5/26/2017	Room 203 Sink	0.114	0.004
5/26/2017	Room 203 Bubbler	0.125	0.002
5/26/2017	Room 201 Sink	0.125	<0.001
5/26/2017	Room 201 Bubbler	0.151	0.001
5/26/2017	Room 202 Sink	0.140	0.002
5/26/2017	Room 202 Bubbler	0.175	0.004
5/26/2017	202-204 Fountain Right	0.100	<0.001
5/26/2017	Room 204 Sink	0.112	0.001
5/26/2017	Room 204 Bubbler	0.119	<0.001
5/26/2017	Room 005 Sink	0.089	0.010
5/26/2017	Room 301 Art Room Sink - Center	0.131	<0.001
5/26/2017	Room 303 Sink	0.145	0.003
5/26/2017	Room 303 Bubbler	0.118	0.002
5/26/2017	305-307 Fountain Left	0.113	0.004
5/26/2017	305-307 Fountain Right	0.090	<0.001
5/26/2017	Mechanical Room Slop Tub	0.102	0.001
5/26/2017	Kitchen Sink - Right	0.172	0.004
5/26/2017	Kitchen Sink - Left	0.282	0.013
5/26/2017	Room 101 Sink	0.155	<0.001
5/26/2017	Room 101 Fountain	0.138	<0.001
5/26/2017	Room 102 Sink	0.175	0.001
5/26/2017	Room 102 Fountain	0.144	<0.001
5/26/2017	102-104 Fountain	0.100	0.002
5/26/2017	Room 104 Sink	0.182	0.003
5/26/2017	Room 104 Bubbler	0.113	0.002
5/26/2017	Room 105 Sink	0.158	0.003
5/26/2017	Room 105 Bubbler	0.135	0.001
5/26/2017	Playground Restroom Fountain	0.063	<0.001
5/26/2017	Room 107 Sink	0.152	0.006
5/26/2017	Room 107 Bubbler	0.140	<0.001
5/26/2017	Room 109 Sink	0.136	<0.001
5/26/2017	Room 109 Bubbler	0.129	<0.001
5/26/2017	Room 111 Sink	0.153	0.001
5/26/2017	Room 111 Bubbler	0.131	<0.001
5/26/2017	Room 113 Sink	0.125	<0.001
5/26/2017	Room 113 Bubbler	0.115	<0.001
5/26/2017	Room 115 Sink	0.202	<0.001
5/26/2017	Room 115 Bubbler	No Sample	
5/26/2017	Room 110 Sink	0.170	0.005
5/26/2017	Room 110 Bubbler	0.147	<0.001
5/26/2017	Room 110 Outside Fountain - Right	0.117	<0.001
5/26/2017	Room 108 Sink	0.186	0.015
5/26/2017	Room 108 Bubbler	0.125	<0.001
5/26/2017	Room 211 Sink	0.113	0.004

